APEX DRILLING INC.

1310 H 181

20 Son IM

Marble Falls, Texas 7860.4

经过程的

Well Impaction Report

Date:	6/17/2015								
Customer Name:		Denise Batiste			Phone	Number	210-393-7111		
Property Address		1705 CR 201 Burnet (House Well)							
		Bettier (nouse wen)			-				
Est. Well Depth:		340'	*						
Well Casing Size:		4ª			W	/ire Size:	10	He-	
Pump Size	Manufacture	: 18GS20	GPM.	25	HP_	2	Ground:	YES	NO
Est. Pump Depth			300,						
Pump Saver : Drop Pipe Size & Type:		YES	NO 11/4		٠				
Amps Pulling:		12							
Main Windings:			2						
Start Windings:			12.0						
Static Water Level:			220						
Pumping Water Level:		2601							
TDS -									
Lat-	30	50	57						
Long -	98	12	1.7						
GPM:	23								
Summary	13								
Recommendations: ** Both wells are tied together**									
Recomme			end a Pump S	aver to	help pro	tect you	pump-		
Well Insp	ected By:	Robert	Johnson						

apex druling inc.

5510 N 281

POWER

Martille Folls, Texas 7(655)

(830)798-2799

Well Inspection Report

Date:	6/17/201	5	-							
Customer Name: Denise		Denise Bar	ise Batiste			e Number	210-393-71	10-393-7111		
MANAGEMENT .		Marie Control of the	705 CR 201 urnet (Creek Well)							
Est. Well I	Depth:	400°	•							
Well Casin	g Size:	6"	•		١	Vire Size:	10	3.		
Pump Size Manufacture: 10		: 10GS15	GPM.	16	HP_	1 1/2	Ground:	YES	NO	
Est. Pump Depth			360'							
Pump Saver : YES Drop Pipe Size & Type:		NO 1 1/4								
Amps Pulling:		11								
Main Windings:		2	10							
Start Windings:		8.7	•							
Static Water Level:		220'	,							
Pumping Water Level:		320'	ı							
TDS -										
Lat-	30] 50	44							
Long -	98	12	12	0						
GPM:	13.7									
Summary:		Well Seal is	s Broken, Ho	lding pipe	up w/	/3/4" Steel	Pipe			
**************************************		No Ball Va	ive to cut wa	ater off						
Recommen	dations:									
Recomme			nd a Pump Sa	aver to he	lp pro	tect you pu	mp			
Well inspected By:		Robert J.	ด์เกระก							