House Well

# STATE OF TEXAS WELL REPORT for Tracking #425182

Owner:

Laura Baker

Owner Well #:

No Data

Address:

1209 E. Sandstone St.

Llano, TX 78643

Grid #:

57-19-2

Well Location:

.7 mi. E of Hwy. 16 on CR 312; .3 mi.

Latitude:

30° 43' 23" N

Longitude:

098° 40' 05" W

Llano, TX

Well County:

Llano

Elevation:

No Data

Type of Work:

**New Well** 

Proposed Use:

Domestic

Drilling Start Date: 6/29/2016

Drilling End Date: 6/29/2016

Borehole:

Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
9.5	0	21
6.75	21	22
6	22	100

Drilling Method:

Air Hammer

Borehole Completion:

Open Hole

Annular Seal Data:

Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
0	3	Cement 1 Bags/Sacks
3	21	Bentonite 4 Bags/Sacks

Seal Method: Poured

Sealed By: Driller

Distance to Property Line (ft.): No Data

Distance to Septic Field or other

concentrated contamination (ft.): No Data

Distance to Septic Tank (ft.): No Data

Method of Verification: No Data

Surface Completion:

Pitless Adapter Used

Water Level:

28 ft. below land surface on 2016-06-29

Packers:

No Data

Type of Pump:

Submersible

Pump Depth (ft.): 80

Well Tests:

Jetted

Yield: 45 GPM

	Strata Depth (ft.)	Water Type
Water Quality:	35	No Data
	90	good (1100 ppmTDS)

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which

contained injurious constituents?: No

Certification Data:

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information:

Virdell Drilling Inc.

111 E. Grayson St. Llano, TX 78643

Driller Name:

James Caleb Virdell

License Number:

59342

Comments:

Open Hole: 22 - 100

# Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

#### Casing: BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
0	2	Topsoil
2	9	Metamorphic Gravel
9	90	Red & Black Metamorphic
90	100	Black Graphite Schist

Dla (in.)	Туре	Material	Sch./Gage		Bottom (ft.)
6	; ;	New Plastic (PVC)	40	-2	22

#### IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157
Austin, TX 78711
(512) 334-5540

### STATE OF TEXAS WELL REPORT for Tracking #84265

Owner:

**David Stewart** 

Owner Well #:

No Data

Address:

P.O. Box 322

Grid #:

57-19-2

Llano, TX 78643

Latitude:

30° 43' 13" N

Well Location:

300' E of Oatman Creek on CR 312: 400' N/E in pasture

TX

Longitude:

098° 40' 09" W

Well County:

Llano

Elevation:

No Data

Type of Work:

**New Well** 

Proposed Use:

Domestic

Drilling Start Date: 6/2/2006

Drilling End Date: 6/2/2006

Borehole:

Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)	
9	0	10	
6.75	10 .	11	
6	11	120	

Drilling Method:

Air Hammer

Borehole Completion:

Open Hole

Annular Seal Data:

Top Depth (ft.) Bottom Depth (ft.)		Description (number of sacks & material)		
0	5	1 Cement		
5	11	3 Bentonite		

Seal Method: Grout

Distance to Property Line (ft.): No Data

Sealed By: Driller

Distance to Septic Field or other concentrated contamination (ft.): No Data

Distance to Septic Tank (ft.): No Data

Method of Verification: No Data

Surface Completion:

Surface Sleeve Installed

Water Level:

18 ft. below land surface on 2006-06-02

Measurement Method: Unknown

Packers:

No Data

Type of Pump:

Solar

Pump Depth (ft.): 110

Well Tests:

**Jetted** 

Yield: 3 GPM

Water Quality:

Strata Depth (ft.)

Water Type

20 - 22

good (1370 ppmTDS)

Chemical Analysis Made:

No

Did the driller knowingly penetrate any strata which

contained injurious constituents?:

No

Certification Data:

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information:

Virdell Drilling Inc.

111 E. Grayson St. Llano, TX 78643

Driller Name:

Lynn Hoy

License Number:

4071

Comments:

No Data

# Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

## Casing: BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description	
0	1	Topsoil	
1	3	Gravel & Clay	
3	120	Red Granite	

New/Used		Setting From/To (ft.)	A
/C +2 - 11	sch 40		The state of the state of

#### IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540