	STATE OF TEXAS WELL REPORT for Tracking #493755			
Owner:	BROOKS PEARCE	Owner Well #:	No Data	
Address:	3101 SHOVEL MOUNTAIN RD. CYPRESS MILL, TX 78663	Grid #:	57-38-6	
Vell Location:	3101 SHOVEL MOUNTAIN RD	Latitude:	30° 26' 03.42" N	
	CYPRESS MILL, TX 78663	Longitude:	098° 16' 10.98" W	
Vell County:	Blanco	Elevation:	No Data	
ype of Work:	New Well	Proposed Use:	Domestic	

Drilling Start Date: 9/10/2018 Drilling End I

Drilling End Date: 9/10/2018

Borehole [.]	Diameter (in.)		Top Depth (ft.)		Bottom Depth (ft.)	
borenole.	9		0		100	
	6.125		100		410	
Drilling Method:	Air Rotary					
Borehole Completion:	Straight Wall					
	Top Depth (ft.)	Bottom Depth (ft.) 100		Description (number of sacks & material) TYPE H CEMENT 9 Bags/Sacks QUICK GEL 2 Bags/Sacks		
Annular Seal Data:	0					
	0 100		00			
Seal Method: Pr	essure		Distar		erty Line (ft.): 1000+	
Sealed By: Dr	iller		Distance concentr	to Septic I ated conta ance to Se	Field or other mination (ft.): 500 ptic Tank (ft.): 500 f Verification: OWNER	
Surface Completion: Surface Sleeve Installed			Surface Completion by Driller			
Water Level:	274 ft. below land	surface o	n 2018-09-12	Measure	ement Method: Electric Line	
Packers:	Burlap at 100 ft. BURLAP & PLASTIC at 120 ft. BURLAP & PLASTIC at 200 ft. BURLAP & PLASTIC at 300 ft.					
Type of Pump:	Submersible			Pump	Depth (ft.): 380	
Well Tests:	Jetted Yield: 10 GPM		10 GPM			

Water Quality:	Strata Depth (ft.) Water Type			
rutor duality.	300 - 400	ELLENBURGER		
	Did the driller kn	Chemical Analysis Made: owingly penetrate any strata which contained injurious constituents?:	No No	
	correct. The driller under	the driller drilled this well (or the well on) and that each and all of the stater erstood that failure to complete the re ned for completion and resubmittal.	monto handia a l	
	correct. The driller under	erstood that failure to complete the rend all of the states ned for completion and resubmittal.	monto handia a l	
	correct. The driller under the report(s) being retur	erstood that failure to complete the re- ned for completion and resubmittal.	monto handia a l	
	correct. The driller under the report(s) being retur Centex Pump & Supp 2520 Hwy. 290 West	erstood that failure to complete the rend all of the states ned for completion and resubmittal. oly, Inc.	ments herein are tru equired items will re	

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	2	TOP SOIL
2	18	BROWN LIMESTONE
18	21	BROWN CLAY
21	80	GRAY LIMESTONE
80	83	RED LIMESTONE
83	120	BROWN LIMESTONE
120	150	WHITE LIMESTONE
150	170	BROWN LIMESTONE
170	210	GRAY LIMESTONE
210	250	BROWN LIMESTONE
250	290	GRAY LIMESTONE
290	320	BROWN LIMESTONE
320	330	GRAY/BROWN LIMESTONE
330	340	BROWN LIMESTONE
340	385	GRAY LIMESTONE
385	410	BROWN LIMESTONE

Casing: BLANK PIPE & WELL SCREEN DATA

Dla (in.)	Туре	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
5	Blank	New Plastic (PVC)	SDR17	2	300
5		New Plastic (PVC)	SDR17 0.032	300	400
5	Blank	New Plastic (PVC)	SDR17	400	410

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540