Section 8

## REPORT SHEET FOR PERCOLATION AND SIX FOOT HOLE TESTING

tal N	umber of	Lots	N	ame of Ap	nme of Applicant										
ame o	f Certifie	d Installer	Responsil	ble for Test	ting Ju	stin	Tim	e E	<u>در .</u>						
	staller Certification No. Installer Signature Say Mullimo J.T.E.  Address HC 44 Box 1634 Romney, wu. 267														
Туре	Lot Number	Percolation Test Results (Minutes per Inch of Fall)				Average Results	Six Foot Hole Results Depth to Water   Depth to Rock			Date Conducted					
System	222	150	135	95	80 95	19.1 16.6	n/A		NA		5-12-06				
Ŧ		95	100	110			1		7		350				
T	224	85	105	90	115	16.4					* */-				
I	225	185	230	230	200	35.2					34 8				
耳	226	165°	200	188	157	24.5									
工	227	130	145	120	115	21.2				1000					
			,		/a V				ļ		ļ				
10	13														
				<u> </u>		<b>}</b>	-	30							
3 K		,	ļ								<del> </del>				
**********					re s.t		1 3		-						
		_		See	- m Have	Led Fo	1.54	22	<b>P</b> _	-	<del></del>				
				1	-			. 5			<u> </u>				
		ļ		4					+						
				*		_				ļ	-				

(Attach additional pages if needed)

Scation 8

## REPORT SHEET FOR PERCOLATION AND SIX FOOT HOLE TESTING

System Number Percolation Test Results (Minutes per Inch of Fall)	Sox 2:	ay had a Capon	Exige bu	Date Conducted 11-2-06 H-2-06
Type Lot System Number Percolation Test Results (Minutes per Inch of Fall)	verage Results I	Six Foot Hol Depth to Water	te Results Depth to Ruck	Date Conducted 11-2-Cb
Type Lot System Number Percolation Test Results (Minutes per Inch of Fall)	verage Results I	Six Foot Hol Depth to Water	te Results Depth to Ruck	Date Conducted 11-2-Cb
System Number Percolation Test Results (Minutes per Inch of Fall)	Results I	Depth to Water	Depth to Rock	Conducted 11-2-Clo
	23.2	.0	0	11-206
2 246 SC 770 73 79 7 1 255 70 70 70 79 7	7			
15-255-140-160-160-129-1	24			H-206
	<u> </u>			T.
				-
		<u> </u>	<u></u>	7.5
	_			
				<u> </u>
				<del>                                     </del>
	<u> </u>		· · · · · ·	<del> </del>
				-
			ļ ·	
			- vs.	
			<b></b>	<del> </del>
	·	<del></del>		+
	السنادة والكام	<del> </del>		-
	<u></u>	·		

(Attach additional pages if needed)



## Hampshire County Health Department

HC 71, Box 9

Augusta, WV 26704 Nursing: (304) 496-9640 Environmental: (304) 496-9641 Fax: (304) 496-9650

December 22, 2006

Hampshire County Planning Commission PO Box 883 Romney, WV 26757

Dear Sirs:

This office has reviewed a plat of survey for WV Hunter, LLC to approve a subdivision called Bluffs on the Potomac Section 8 located on Graces Cabin Road, and further referenced as Tax District Romney, Tax Map 31, Parcel 3, 2, and 1, and Tax Map 20 Parcels 2 and 1, Deed book 436, Page 638. This subdivision section consists of 26 lots containing 719.47 acres. All lots contain a sewage disposal area of 10,000 square feet where no development or structures other than the septic system shall be permitted. These lots are to be developed with individual wells and septic systems to serve single family dwellings.

Percolation test results are within limits as set forth by West Virginia CRS 16-1. Six foot soil observation holes indicate no restrictions due to water table or shallow bedrock within the designated sewage disposal area except as noted on the Health Department subdivision application.

The plat of survey dated 10/23/06, is hereby approved by the Hampshire County Health Department. Any changes or revisions to the Health Department stamped and signed plat, or subsequent final plats approved based upon the approved plat, will make this approval null and void.

This approval is not permit for individual water systems or individual sewer systems. Applications for permits must be made separately to the Hampshire County Health Department.

Sincerely

Terry Mayhew, RS

CC: WV Hunter, LLC