Lot 21

REQUEST FOR SITE APPROVAL

To: Hardy County Health Department, Moorefield, WV
From: Name: Melbourne Prop. /Phone 854-2957
Address P.O. Box 567 Capon Bridge WV 26711
RE: Property Location Lost River for Whetzel Rd.
Request is hereby made for a site investigation to determine the suitability of the subject property as a site for small sewage system indicated below:
(/) Septic System () Pit Privy () Vault Privy () Other
The results of a percolation test conducted in accordance with the requirements of Design Standards for Small Septic Tank Systems follows:
Depth of test holes: #1 24", #2 ((, #3 (, #4 () inches.
Time for water to fall 6 inches in test hole #1 180 minutes #2 240 minutes #3 180 minutes #4 120 minutes Total 30 minutes.
A test hole bored or dug 6 feet deep () has () has not been provided to help determine the depth to bedrock and ground water table.
On the back of this form a plot layout has been sketched showing the property lines and relative locations of buildings, water supplies, percolation test holes, six ft. hole, and other pertinent features.
I (we), the undersigned, certify that the information contained herein is correct and accurate to the best of my (our) knowledge. It is further understood that this form is not an application for a permit, and subsequent acceptance of this site by the designed health department, does not constitute a permit to install a sewage system.
Owner's Signature A Drinda & Stratten Date 6/3/05
Percolation test conducted by: Name: Neadly Special Serves
Address: P.O. Box 188 Capon Bridge W 24711
Date: 6608 / Signature Nendell Meade
For Health Department Use Only
This is to certify that the Mardy County Health Department reviewed the contents of this form and conducted a site visit on subject property. Based on the information provided it is the opinion of the undersigned that this site ()-48 () is not Suitable for the installation of the small sewage system indicated.
Signature and Title Willis Ours / Sarute: Date 7/6/05