REQUEST FOR SITE APPROVAL

TO: Hardy County Health Department, Moorefield, W.V.

FROM:	Name Hunter Co. of WV	Phone 1-304-262-2770			
	Address 1800 West King St.	Martins	WV	25401	
RE:	Property Location Ashton Wood	Is Sub.			_

Request is hereby made for a site investigation to determine the suitability of the subject property as a site for the small sewage system indicated below:

(-) Septic System () Pit Privy () Vault Privy () Other wowr

The results of a percolation test conducted in accordance with the requirements of Design Standards for Small Septic Tank Systems follows:

Depth of test holes: #124, #224, #324, #424 inches.

Time for water to fall 6 inches in test hole #1 /80 minutes #2 /80 #3 2/0 #3 2/0 #4 2/0 #4 2/0 #4

TOTAL

750

Minutes.

A test hole bored or dug 6 feet deep (has () has not been provided to help dettermine the depth to bedrock and ground water table.

On the back of this form a plot layout has been sketched showing the property lines and relative locations of buildings, water supplies, percolation test holes, six ft. hole, and other pertinent features.

I (we), the undersigned, certify that the information contained herein is correct and accurate to the best of my (our) knowledge. It is further understood that this form <u>is not</u> an application for a permit, and subsequent acceptance of this site by the designated health dept. <u>does not</u> constitute a permit to install a sewage system.

Owner's signature Hut	- Wilson	Date 3-26-03
Percolation test conducted by:		art
	Address Rt 1 Box 16	3AZ Faw Paw WU
Date_3-24-03	-1 0	Hart 25434
		.4

FOR HEALTH DEPT. USE ONLY

This is to certify that the Hardy County Health Department reviewed the contents of this form and conducted a site visit on subject property. Based on the information provided it is the opinion of the undersigned that this site (1) is (1) to not suitable for the installation of the small sewage system indicated,

morne K. Hompson K.S. Date 4-15-03 Signature Title Sandanc



REQUEST FOR SITE APPROVAL

Hardy County Health Department, Moorefield, W.V. TO:

Name Hunter Co. of WV Phone 1-304-262-2770 FROM: Address 1800 West King St. Martins WV 25401 Property Location Ashton Woods Sub. RE:

Request is hereby made for a site investigation to determine the suitability of the subject property as a site for the small sewage system indicated below:

(-) Septic System () Pit Privy () Vault Privy () Other wowe

The results of a percolation test conducted in accordance with the requirements of Design Standards for Small Septic Tank Systems follows:

Depth of test holes: #124, #224, #324, #424 inches.

Time for water to fall 6 inches in test hole #1____ 210 minutes #2

240

#3

#4

11

11

Minutes. 4/min Prik

Lot 94 TOTAL

A test hole bored or dug 6 feet deep (/ has () has not been provided to help determine the depth to bedrock and ground water table.

On the back of this form a plot layout has been sketched showing the property lines and relative locations of buildings, water supplies, percolation test holes, six ft. hole, and other pertinent features.

I (we), the undersigned, certify that the information contained herein is correct and accurate to the best of my (our) knowledge. It is further understood that this form is not an application for a permit, and subsequent acceptance of this site by the designated health dept. does not constitute a permit to install a sewage system.

Owner's signature Hunty	Wilson	Date_3	-25-03
Percolation test conducted by:	Name Billy (1. Hart	
	Address Rt 1 Bo	× 163A2	Paw Paw WU
Date 3-25-03	Signature Billy	& Hart	25434
	1.		

FOR HEALTH DEPT, USE ONLY

This is to certify that the Hardy County Health Department reviewed the contents of this form and conducted a site visit on subject property. Basad on the information provided it is the opinion of the undersigned that this site (W is the suitable for the installation of the small sewage system indicated

mpron, R.S. Date 4-15-03 Signature Somitar Title .

