

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

(8)

1 WELL TAG NO. D 0088277

Drilling Permit No _____

Water right or injection well # _____

2 OWNER:

Name MYKEE I LLC.Address 435 WOOD VIEW RD.City SANDPOINT State ID Zip 83864

3 WELL LOCATION

Twp 54 North ☒ or South ☐ Rge 4 East ☐ or West ☒Sec 10 1/4 N/W 1/4 S/W 1/4County BONNERLat 48 ° 2.1803 ' (Deg. and Decimal minutes)Long 116 ° 49.6106 ' (Deg. and Decimal minutes)Address of Well Site SANDPOINT RD.City PRESTON RIVERLot 8 Bldg _____ Sub Name SANDPOINT ESTATES

4 USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation ☐ Thermal ☐ Injection

5 TYPE OF WORK:

☒ New well ☐ Replacement well ☐ Modify existing well☐ Abandonment ☐ Other _____

6 DRILL METHOD:

☒ Air Rotary ☐ Mud Rotary ☐ Cable ☐ Other _____

7 SEALING PROCEDURES

Seal material	From (ft)	To (ft)	Quantity (lbs or ft)	Placement method/procedure
BENTONITE CLAY	0	18	500 LBS.	OVERBORE DRY PACK

8 CASING/LINER

Outer Dia. (in)	From (ft)	To (ft)	Gauge Schedule	Material	Casing Liner	Threaded	Welded
6	+2	198	.250"	STEEL	☒	☐	☒

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 198'9 PERFORATIONS/SCREENS: PERF @ 200Perforations ☒ Y ☐ N Method AIR PERFORATORManufactured screen ☐ Y ☒ N Type _____

Method of installation _____

From (ft)	To (ft)	Slot size	Number/ft	Diameter (nominal)	Material	Gauge or Schedule
198	199	1/4" x 1"	48	6	STEEL	.250"

Length of Headpipe _____ Length of Tailpipe _____

Packer ☐ Y ☒ N Type _____

10 FILTER PACK

Filter Material	From (ft)	To (ft)	Quantity (lbs or ft)	Placement method
-----------------	-----------	---------	----------------------	------------------

11 FLOWING ARTESIAN:

Flowing Artesian? ☐ Y ☒ N Artesian Pressure (PSIG) _____

Describe control device _____

12. STATIC WATER LEVEL and WELL TESTS:

Depth first water encountered (ft) 170 Static water level (ft) 170Water temp (°F) COLD Bottom hole temp (°F) COLDDescribe access port WELDED PLATE

Well test:

Drawdown (feet)	Discharge or yield (gpm)	Test duration (minutes)	Test method:			
200	35	60	Pump	Bailer	Air	Flowm. orifice
			☐	☐	☒	☐

Water quality test or comments: CLOUDY, PUMP TILL CLEAN

13. LITHOLOGIC LOG and/or repairs or abandonment:

Bore Dia. (in)	From (ft)	To (ft)	Remarks, lithology or description of repairs or abandonment, water temp.	Water
10	0	1	TOP SOIL	
8	1	18	COARSE SAND & LARGE COBBLES	X
	83	170	CEMENTED SAND, CLAY, GRAVEL	
	170	200	" " W/WATER	X

208-263-5974

Mark Pitts
Robin PittsServing
North Idaho
Over 20 YearsAAA
**SWEETWATER
DRILLING**DRILLING • PUMPS • WATER TREATMENT
Complete Systems • From the Well To The House
435 Woodview Rd • Sandpoint, ID 83864Completed Depth (Measurable) 200'Date Started 6/25/21Date Completed 6/28/21

14. DRILLER'S CERTIFICATION:

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name AAA SWEETWATER DRILLING Co No 509Principal Driller Mark Pitts Date 7-7-21Driller [Signature] Date 6/29/21

Operator II _____ Date _____

Operator I _____ Date _____

* Signature of Principal Driller and rig operator are required