

STATE OF TEXAS WELL REPORT for Tracking #485164

Owner:	Ryan Jordan	Owner Well #:	No Data
Address:	PO Box 1841 Mason, TX 76856	Grid #:	56-24-1
Well Location:	1/2 Mile East of Art on Hwy 29. Location is North of 29 1/2 in pasture. Art, TX	Latitude:	30° 44' 38.81" N
		Longitude:	099° 06' 20.76" W
Well County:	Mason	Elevation:	No Data

Type of Work:	New Well	Proposed Use:	Stock
---------------	-----------------	---------------	--------------

Drilling Start Date: **7/23/2018** Drilling End Date: **7/23/2018**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	9	0	27
	6.25	27	125

Drilling Method: **Air Hammer**

Borehole Completion: **Open Hole**

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	-2	27	Cement 5 Bags/Sacks

Seal Method: **Poured**

Sealed By: **Driller**

Distance to Property Line (ft.): **80+**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion:	Surface Sleeve Installed	Surface Completion by Driller
---------------------	---------------------------------	--------------------------------------

Water Level:	32 ft. below land surface on 2018-07-23	Measurement Method:	Steel Tape
--------------	--	---------------------	-------------------

Packers: **No Data**

Type of Pump: **No Data**

Well Tests: **Jetted** **Yield: 12 GPM**

Water Quality:

Strata Depth (ft.)	Water Type
71 - 105	No Data

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Magill Drilling & Water Well Service**

**PO Box 46
Castell, TX 76831**

Driller Name: **Zane Magill**

License Number: **4168**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	1	Topsoil
1	26	Red Sandy Gravel
26	125	Red Granite

Casing:
BLANK PIPE & WELL SCREEN DATA

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
6	Blank	New Plastic (PVC)	40	-2	27

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540**