STATE OF TEXAS WELL REPORT for Tracking #595835			
Owner:	William Bernecki	Owner Well #:	8765
Address:	1705 Waterstone Parkway Boerne , TX 78006	Grid #:	68-04-9
Well Location:		Latitude:	29° 53' 36" N
	Boerne, TX 78006	Longitude:	098° 31' 59" W
Well County:	Kendall	Elevation:	1112 ft. above sea level
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Start Date: 12/20/2021 Drilling End Date: 12/21/2021

	Diameter (in.) Top D	epth (ft.)	Bottom Depth (ft.)
Borehole:	8		0	440
Drilling Method:	Air Rotary			
Borehole Completion:	Perforated or Slotted			
	Top Depth (ft.)	Bottom Depth (ft.)	De	escription (number of sacks & material)
Annular Seal Data:	0	170		Cement 10 Bags/Sacks
	0	170		Grout 16 Bags/Sacks
Seal Method: Pr	essure	Di	stance to P	roperty Line (ft.): No Data
Sealed By: Dr	riller Distance to Septic Field or other concentrated contamination (ft.): 150			
			Distance to	Septic Tank (ft.): No Data
			Metho	od of Verification: Estimated
Surface Completion:	Surface Sleeve In	nstalled	S	urface Completion by Driller
Water Level:	280 ft. below land surface on 2021-12-20			
Packers:	Rubber at 170 ft.			
Type of Pump:	Submersible			
Well Tests:	Estimated	Yield: 20+ GPN	I	

	Strata Depth (ft.)	Water Type		
Water Quality:	No Data	No Data		
		Chemical Analysis Mad	e: No	
		vingly penetrate any strata whick contained injurious constituents		
Certification Data:	driller's direct supervision correct. The driller under	e driller drilled this well (or the v) and that each and all of the sta stood that failure to complete th ed for completion and resubmitta	atements here e required ite	rein are true and
Certification Data: Company Information	driller's direct supervision correct. The driller under the report(s) being return) and that each and all of the sta stood that failure to complete th ed for completion and resubmitta	atements here e required ite	rein are true and
	driller's direct supervision correct. The driller under the report(s) being return) and that each and all of the sta stood that failure to complete th ed for completion and resubmitta	atements here e required ite	rein are true and
	driller's direct supervision correct. The driller under the report(s) being return TR Drilling & Service I PO Box 733) and that each and all of the sta stood that failure to complete th ed for completion and resubmitta _LC	atements here e required ite	rein are true and
Company Information	driller's direct supervision correct. The driller under the report(s) being return TR Drilling & Service I PO Box 733 Boerne, TX 78006) and that each and all of the sta stood that failure to complete th ed for completion and resubmitta LLC License	atements he e required it al.	rein are true and ems will result in 2901

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	2	Topsoil
2	8	Gold rock, orange red clay
8	19	Orange yellow tan clay
19	29	Shale gray rock, brown rock
29	32	Tan/ceam
32	40	Cream
40	49	Hard cream, light brown
49	55	Beige rock
55	68	Dark yellow rock
68	75	Dark gray
75	83	Dark gray and light gray
83	85	Dark gray, dry shale
85	94	Gray/tan oyster rock
94	100	Medium gray rock
100	110	Gray with gray shale
110	148	Blue shale
148	180	Gray with tan rock

Casing: BLANK PIPE & WELL SCREEN DATA

Dla (in.)	Туре	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
4.5	Blank	New Plastic (PVC)	SDR17	0	380
4.5	Screen	New Plastic (PVC)	SDR17 0.032	380	420
4.5	Blank	New Plastic (PVC)	SDR17	420	440

180	200	Gray and brown rock
200	220	Light grayish tan
220	250	Tan sandstone
250	262	Red, purple, green rock
262	293	Tan, green, brown
293	322	Red, green rock
322	340	Tan/yellow sandstone
340	385	Red, green, yellow
385	400	Cream, light brown
400	420	Cream, tan, yellow
420	435	Red sandstone
435	440	Gold

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540