



PREPARED FOR: Daniel C. McGinnis - Seller Jaime Vasquez & Veronica Leal Vasquez - Buyers

FIELD NOTES TO DESCRIBE

Tract 95 (10.29 Acres) of Rancho Real Subdivision Unit III according to the plat thereof recorded in Volume 1, Pages 80-87 of the Plat Records of Real County, Texas, and being more particularly described as follows:

BEGINNING: At a 5/8" iron pin found in the Northwest line of Tract 184 for the East

corner of Tract 94B and the South corner of this tract from which a 5/8 " iron pin found for the South corner of Tract 94A bears \$ 21° 11' 07" W 331.42

feet:

THENCE: N 50° 11′ 50″ W 1601.21 feet, at 1148.03 feet pass a found 3/4″ iron pin, at

1218.77 feet pass a 5/8" found iron pin and at 1500.12 feet pass a found 3/4" iron pin, continuing to the North corner of Tract 94B and the West

corner of this tract;

THENCE: With Bluff Creek and the Southeast line of Tract 127 and the Northwest line

of this tract as follows:

N 54° 25' 33" E 76.84 feet to an angle point; N 48° 28' 01" E 159.16 feet to an angle point;

N 63° 13' 36" E 142.46 feet to the East corner of Tract 127, the Southwest

corner of Tract 128 and the North corner of this tract;

THENCE: S 70° 13' 15" E 163.51 feet with Bluff Creek to the South corner of Tract 128

and the West corner of Tract 96 and an angle point of this tract;

THENCE: With Bluff Creek and the Southwest line of Tracts 96-99 as follows:

S 38° 17' 29" E 565.71 feet to the South corner of Tract 96 and the West

corner of Tract 97 and an angle point of this tract;

S 32° 14' 45" E 193.10 feet to the South corner of Tract 97 and the West

corner of Tract 98 and an angle point of this tract;

\$ 37° 57' 45" E 143.90 feet to an angle point; \$ 42° 51' 09" E 236.30 feet to an angle point;

S 50° 36' 44" E 201.56 feet to the South corner of Tract 100 and the East

corner of this tract;

THENCE: \$ 29° 20' 11" W 186.03 feet with the Northwest line of Tract 184 to the POINT

OF BEGINNING.

Bearings shown herein are from GPS observations Texas Coordinate System NAD (83).

I hereby certify that the foregoing field note description and accompanying plat were prepared from an actual survey performed on the ground, under my supervision and that to the best of my belief and knowledge they are true and correct.

w M

I May M

John Howard, R.P.L.S. No. 4611

Howard Surveying, LLC 402 State Highway 173 South

Hondo, Texas 78861 (830) 426-4776