TO:	Hardy County Health Department, Moorefield, W.V.
FROM:	Name MelBourne Prop. Phone 856-2957
	Address P.O BOX 567 CAPON BRidge, W. UA. 26711
RE:	Property Location 4 miles ow Neepmore RD.
of the	Request is hereby made for a site investigation to determine the suitability subject property as a site for the small sewage system indicated below:
() [‡] Se	ptic System () Pit Privy () Vault Privy () Other Site Approuah
	The results of a percolation test conducted in accordance with the sments of Design Standards for Small Septic Tank Systems follows:
	Depth of test holes: #1 24", #2 24", #3 24", #4 24" inches.
	Time for water to fall 6 inches in test hole #1 $\frac{180}{42}$ minutes #2 $\frac{144}{180}$ " TOTAL $\frac{180}{144}$ Minutes.= 31
provide	A test hole bored or dug 6 feet deep () has () has not been of the delicermine the depth to bedrock and ground water table. We per the
propert	On the back of this form a plot layout has been sketched showing the y lines and relative locations of buildings, water supplies, percolation les, six fr. hole, and other pertinent features.
that th	I (we), the undersigned, certify that the information contained herein is and accurate to the best of my (our) knowledge. It is further understood is form is not an application for a permit, and subsequent acceptance site by the designated health dept. does not constitute a permit to a sewage cystem.
Owner's	signaturo_ 663
Percola	tion test conducted by: Name Meade's Special Services
	Address P. U. Box 188 Capon Bridge, W. Un. 2676
Date 1-	24-03 Signature Wendell meade
-	5:
	FOR HEALTH DEPT. USE ONLY
Based or this sit system i	This is to certify that the Hardy County Health Department reviewed tents of this form and conducted a site visit on subject property. I the information provided it is the opinion of the undersigned that is () is () is not suitable for the installation of the small sewage indicated.
Signatur	e Lomoine K. Mongron Date 2-1-03
71+10	do the