



PETERS'

DRILLING & PUMP SERVICE

WELL PRODUCTION REPORT

P.O. Box 1546
Grass Valley, CA 95945
Phone (530) 273-8136 FAX (530) 273-1213

CUSTOMER:

Customer: Erin Wen
Address: 226 Rhode Island St.
Grass Valley, CA 95945

Property Address: 10438 Lazy Valley
City: Penn Valley
County: Nevada
Assessor's Parcel#: 051 - 140 - 011

WELL TEST INFORMATION:

Date of Test: 12/27/2021
Casing Size: 6" PVC
Pressure Tank: 86 Gallon
Pipe Down Well: 1" Poly
Pump HP and Type: 3/4 HP
Depth of Well: 72'
Holding Tank: None
Holding Tank Pump: None
Safety Controls: None
Beginning Static Level: Not Measured
Ending Static Level: Not Measured
Filter System: Softener, not plugged in and bypassed
Lab Test(s):
Water Potability: Taken
Water Mineral: None Ordered

Time:	Yield:
12:45	23.1
1:00	23.1
1:15	23.1
1:30	23.1
1:45	23.1
2:00	23.1
2:15	23.1
2:30	23.1
2:45	23.1
3:00	23.1
3:15	23.1
3:30	23.1
3:45	23.1

Sustained Well Yield: 23.1+ Gallons Per Minute

Other comments:

Well tested for (hours): 3 Hours
Tested by: Dave Wood
Technician: Dave Wood MD

*Well yield indicated is guaranteed for the date of the test only. You should be aware that the yield may not be constant over time due to uncontrollable geological, climatological, and underground water supply circumstances. Therefore, there is no assurance that the well yield will be reproducible at a later date.

** Each county has an acceptable minimum yield. Please check with the county that pertains to this parcel in order to determine if the yield is acceptable.



Sample Results

Peters Drilling and Pump Service
P.O.Box 1546
Grass Valley, CA 95945

Work Order: GDL1073
Received: 12/28/21 16:10
Reported: 12/29/21 11:30

Private Client

Sample Site: 10438 Lazy Valley P.V
Sample Number GDL1073-01

Date Collected: 12/28/2021 13:45
Collected by: DW
Title 22 Designation:

No Chlorine Detected								
	Result	Units	Reporting Limit	Method	Analyst Initials	Bacti Setup Time	Analysis Date	
E.coli	<1.0	MPN/100 mL	1.0	SM 9230 B - 2004 Colilert 18	AB	12/28/21 16:32	12/29/21	
Total Coliform	1.0	MPN/100 mL	1.0	SM 9230 B - 2004 Colilert 18	AB	12/28/21 16:32	12/29/21	

Total Coliform bacteria were detected in this sample. The water supply may not be adequately protected from potentially harmful contamination. This result does not meet public health or lending institution guidelines.

Term and Qualifier Definitions

Item	Definition
ND	None detected at or above the reporting limit

Justin Smith
Laboratory Manager

Integrating people, land and water.

1188 East Main Street, Grass Valley, CA 95945

Phone: (530) 273-7284 | Fax: (530) 273-9507 | www.cranmerengineeringinc.com | E.L.A.P. Certification No. 1936

Sampling • Analytical Testing • Courier Service • System Operators • Engineering • Surveying • Technical Reporting • Planning • Construction Mgmt.