STATE OF TEXAS WELL REPORT for Tracking #602092

Owner: Owner Well #: 24 **GK Ranch Sales, LLC**

Address: 10670 N Central Expressway Grid #: 68-18-4

Suite 210

Dallas, TX 75231 Latitude: 29° 42' 10.4" N

Well Location: 9261 State Hwv 46 Longitude: 098° 51' 09.1" W Pipe Creek, TX 78063

> Elevation: No Data

Well County: **Bandera**

24 Number of Wells Drilled:

Type of Work: **New Well** Proposed Use: **Domestic**

Drilling Start Date: 12/1/2021 Drilling End Date: 12/7/2021

Diameter (in.) Top Depth (ft.) Bottom Depth (ft.) Borehole: 9 0 900

Drilling Method: Air Rotary

Filter Packed Borehole Completion:

Top Depth (ft.) Bottom Depth (ft.) Filter Material Size Filter Pack Intervals: 620 900 Gravel

Top Depth (ft.) Bottom Depth (ft.) Description (number of sacks & material) Annular Seal Data: Cement 4 Bags/Sacks 0 10

10 590 Bentonite 180 Bags/Sacks 590 620 **Cement 8 Bags/Sacks**

Seal Method: Tremie Distance to Property Line (ft.): 50+

Sealed By: Driller Distance to Septic Field or other concentrated contamination (ft.): 100+

Distance to Septic Tank (ft.): 50+

Method of Verification: Owner

Surface Sleeve Installed Surface Completion: Surface Completion by Driller

Water Level: 632 ft. below land surface on 2022-01-11 Measurement Method: Electric Line

Packers: No Data

Type of Pump: No Data

Well Tests: **Pump** Yield: 5 GPM Plug Information:

Description (number of sacks & material)	Top Depth (ft.)	Bottom Depth (ft.)	
Cement	900	1010	

Water Quality:

Strata Depth (ft.) Water Type	600 - 900	Glen Rose
O D	Strata Depth (ft.)	Water Type

Chemical Analysis Made: Yes

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the

driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in

the report(s) being returned for completion and resubmittal.

Company Information: Texan Water

161 Industrial Loop

Fredericksburg, TX 78624

Driller Name: Brice Bormann License Number: 54855

Apprentice Name: Justin Bounds Apprentice Number: 60110

Comments: No Data

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	80	White and tan limestone
80	110	Brown and tan limestone w/ streaks of clay
110	180	Tan and grey limestone
180	435	Grey limestone
435	485	Grey sandy limestone
485	500	Tan and grey sandy limestone
500	535	Grey limestone
535	560	Grey limestone and clay
560	575	Brown and tan limestone
575	615	Grey shale and clay
615	840	Grey limestone
840	880	Brown, white, and grey limestone
880	900	Grey limestone
900	940	Shale

Casing: BLANK PIPE & WELL SCREEN DATA

Dla (in.)	Туре	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
4.5	Blank	New Plastic (PVC)	SDR17	0	800
4.5	Screen	New Plastic (PVC)	SDR17 0.032	800	900

940	1000	Brown, white, and tan limestone
1000	1010	Grey clay

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540