




TO ALL PARTIES INTERESTED IN PREMISES SURVEYED:

This is to certify, that on this date, under my supervision, a careful and accurate survey has been made on the ground of property located at 170 Cr. Rd. 265, in Priddy, Mills County, Texas, and is described as follows:

Legal Description: See Field Note Description.



LEGEND


- Iron Pipe Found
- Pipe-Fence Corner
- Iron Rod Set-5/8"
- Iron Rod Found-1/2"
- Post-Fence Corner
- W Water Well
- P Power Pole
- △ Set 60d Nail
- () Adjoiner Call

"TO THE LIENHOLDERS AND/OR THE OWNERS OF THE PREMISES
SURVEYED AND TO THE TITLE INSURANCE COMPANY RELYING HEREON"

The undersigned does hereby certify that this survey was this day
made on the ground of the property legally described hereon
and is correct and that there are no visible discrepancies,
conflicts, encroachments, overlapping of improvements, visible
easements or roadways, except as shown hereon and that
said property has frontage on a public roadway, except as
shown hereon.

Jose R. Lopez

Registered Professional Land Surveyor
Texas Registration Number 6054



Seller: **Monica C. Cox & Laura E. McMullen**

Solum Surveying, Inc.

SURVEYING & MAPPING
P.O. BOX 2220 ALICE, TX 78333

solum.survey@gmail.com

Firm No. 10193847

Scale: 1" = 600'

Date: March 29, 2025

Bk & Pg.: 25-1711

Drawn by: J