



Bee Cave Drilling, Inc.

185 Angelfire Dr. Dripping Springs, TX 78620

512-894-4221 www.beecavedrilling.com

Maintenance Report

Customer Name Englehart, Janice this account - 19935 Date of service 12/01/2022 Technician Zachary Hernand

Property Address or description 401 Lost Valley Rd.

Gate codes or locks 1401 Contact Contract dates from to

Power Supply	Voltage (with pump running) L1 to G 120.6 L2 to G 120.4 L3 to G L1 to L2 239 L2 to L3 Issues? None Recommendations None Actions taken Sprayed for ants
Submersible Pump Control	Condition Good 3/4hp Clamshell Recommendations None Actions taken Sprayed for ants
Submersible Pump	Amp draw 7.9 Normal range for this pump 6.4-8.0 Result Normal Recommendations Sprayed for ants
Pressure Switch	Condition Good Recommendations None Actions Taken Sprayed for ants
Pressure Tank	Precharge 30psi Recommendations Good
Booster Pump	Amp draw N/A Normal range of that pump Result Sub Pump Amp Draw Recommendations
Booster Control	Condition Controller Condition Recommendations
Storage Tank	Condition N/A N/A Recommendations
Freeze Protection	Condition Adequate Recommendations
Comments	The cap for Schrader valve on pressure tank was missing so I replaced it. No other issues found, system is operating normally at present time.