

Other Options

[Return to menu](#)
[Plot this site in State Library Digital Atlas](#)
[Plot this site in Google Maps](#)
[View scanned well log \(6/25/2008 8:55:55 AM\)](#)

Section 7: Well Test Data

Total Depth: 160
Static Water Level: 85
Water Temperature:

Section 1: Well Owner(s)

1) GANNON, GREG (WELL)
1199 HARD ROCK ROAD
CORVALLIS MT 59828 [07/27/2002]
2) GANNON, GREG (MAIL)
858 CANYON VIEW LOOP
HAMILTON MT 59840 [No Date]

Air Test *

20 gpm with drill stem set at 155 feet for 1 hours.
Time of recovery 0.66 hours.
Recovery water level 85 feet.
Pumping water level _ feet.

Section 2: Location

Township	Range	Section	Quarter Sections	
07N	20W	35	SE¼ SW¼ SE¼ NE¼	
County			Geocode	
RAVALLI				
Latitude	Longitude	Geomethod	Datum	
46.32	-114.0536	NAV-GPS	NAD83	
Ground Surface Altitude	Ground Surface Method	Datum	Date	
3806.012	DEM		7/25/2012	
Addition	Block	Lot		

** During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.*

Section 3: Proposed Use of Water

DOMESTIC (1)

Section 4: Type of Work

Drilling Method: ROTARY
Status: NEW WELL

Section 5: Well Completion Date

Date well completed: Saturday, July 27, 2002

Section 6: Well Construction Details

Borehole dimensions

From	To	Diameter
0	160	6

Casing

From	To	Diameter	Wall Thickness	Pressure Rating	Joint	Type
-1.5	160	6	0.250			STEEL

Completion (Perf/Screen)

From	To	Diameter	# of Openings	Size of Openings	Description
160	160	6			OPEN BOTTOM

Annular Space (Seal/Grout/Packer)

From	To	Description	Cont. Fed?
0	0	BENTONITE	

Section 8: Remarks

Section 9: Well Log

Geologic Source

Unassigned

[illegible]

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name: AARON WEIDOW
Company: AQWA DRILLING LLC
License No: WWC-589
Date Completed: 7/27/2002