

SERVICE INVOICE

Luke Installer II OS0019904

Service Location Billing Information Ticket Information

Hood, Helen 948 Middle Windsor Rd McGregor, TX 76657 254-840-4114 dwp551@yahoo.com

Waco McLennan Co Health

Print Date: 2 Job Date: 0 Ticket: 3

2/21/2024 02/13/2024 345091

Technician: Devyn Jenkins

PO Number:

Reason For Call: Contract Inspection Visit 3 of 3

Notes

Estimate for riser replacement is ~ \$559.87 + tax

Scope of work

- 1. Perform repairs on the system according to TCEQ Ch. 285 regulation and manufacturers recommendation.
- 2. Filing of all necessary paperwork with the county if applicable.
- 3. Clean up work site and dispose of refuse.
- 4. Ensure complete system performance by testing. The determination of performance is based on the system condition at the time of the repair.
- 5. Honor warranty on parts

Warranty is an extension of the manufacturer's warranty. It covers any manufacturer's defects in workmanship. It also covers negligence on the part of JS&RWS at the time of installation. Warranty does not cover damage to the system on the part of; acts of nature, vandalism, or negligence, abuse, misuse, or overloading, etc. by the home owner or their associates. Warranty is a parts warranty only. Labor is not warrantied. This is not a system performance guarantee.

Owner shall provide

- 1. A clear and unobstructed work area. This includes but is not limited to fences, sidewalks, dog kennels, and landscaping. If the site is obstructed upon arrival, we will apply the cost associated with removal of the obstructions to the final invoice. JerNan Septic and Rainwater Solutions and its sub-contractors are not responsible for the costs associated with damaged sidewalks, driveways, fences, trees or other more permanent obstructions, incurred during the course of construction.
- 2. Water and spigot to wash down tanks and components.
- 3. Access to power supply for control of the system during repair.
- 4. Haul off of soil spoils.
- 5. Costs associated with the excavation of solid rock and backfill material necessary for the removal and replacement of soils.
- 6. Costs associated with the revegetation of landscaped areas, replacement of gravel in driveways and walkways, etc.
- 7. Costs associated with the damages to any unmarked underground utilities both public and private.
- 8. Costs associated with the discovery of any unknown variables that may be encountered during the course of construction or repair.

Service Recommended but Declined	Summary		
	Sub Total	\$0.00	
	Tax	\$0.00	

Amount Paid Balance Due \$0.00 \$0.00 \$0.00

Inspection Information

EVALUATION:

Section	ltem	Value
A1. Inspection Report	Permit #	7625
A1. Inspection Report	Agency Name	Waco McLennan Co Health
A1. Inspection Report	County	Waco McLennan Co Health
A1. Inspection Report	Maint Provider	Lucas
A2. Inspection Report	Mfg. Brand	NAYADIC- POC her daughter- carol 936-581-2082
A2. Inspection Report	Contract Dates	02/10/2024 - 02/10/2025
B. Aerators	Aerators	OP
B. Aerators	Air Filter	OP
B. Aerators	Diffusers	OP
B. Aerators	Return Airline	OP
B. Aerators	Pressure Switch	OP
C. Distribution System	Distribution System	OP
C. Distribution System	Odor	No
C. Distribution System	Distribution Pump	OP
C. Distribution System	Spray Heads	OP
C. Distribution System	Spray Field Vegetation	OP
C. Distribution System	Needs Mowing	No
E. Electrical Circuits	Electrical Circuits	OP
E. Electrical Circuits	Electrical Connections Panel	OP
E. Electrical Circuits	Electrical Connections Panel Corrosion	No
E. Electrical Circuits	Electrical Connections Alarm Indicator Visual	Non-OP

12	25/24, 9:04 AM		Jernan Sepuc & Rainwater Solutions work Order
	E. Electrical Circuits	Electrical Connections Alarm Indicator Audio	OP
	E. Electrical Circuits	Electrical Circuits Timeclock	OP
	E. Electrical Circuits	Electrical Connections Pump	OP
	E. Electrical Circuits	Electrical Connections Pump Corrosion	No
	E. Electrical Circuits	Electrical Connections Pump On/Off Float	OP
	E. Electrical Circuits	Electrical Connections Pump Alarm Float	OP
	F. Disinfection Device	Disinfection Device	OP
	F. Disinfection Device	Chlorine Supply	OP
	F. Disinfection Device	Chlorine Residual mg/L	0.1
	H. Tank Access	Lid	Secure
	H. Tank Access	Fall Restraints	No
	J. Test Results	Tank 1 Able to Test	Yes
	J. Test Results	Treatment Odor	No
	J. Test Results	Treatment Able to test	Yes
	J. Test Results	Pump Tank What Color	Clear

Report Comments Safety screw port in use, recommend new riser

Technician Signature

K. Comments



Images



