STATE OF TEXAS WELL REPORT for Tracking #334696

Owner: Don Smith Owner Well #: 1

Latitude:

Longitude:

218 W Broadway Address:

Grid #: 67-63-9

Cuero, TX 77954

29° 01' 35.07" N

Hwy 87 South Well Location: Cuero, TX 77954

097° 09' 52.77" W

Stock

DeWitt Well County:

Type of Work: New Well

Elevation: No Data

Drilling Start Date: 6/21/2006

Proposed Use:

Drilling End Date: 6/21/2006

Borehole:

Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)	
7.875	0	10	
6.75	10	150	

Drilling Method:

Mud (Hydraulic) Rotary

Borehole Completion:

Straight Wall

Annular Seal Data:

-1	20	13 cement	
Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)	

Seal Method: Slurry

Distance to Property Line (ft.): 110

Sealed By: H. Rangnow

Distance to Septic Field or other concentrated contamination (ft.): no septic

Distance to Septic Tank (ft.): No Data

Method of Verification: D Smith - Measure

Wheel

Surface Sleeve Installed Surface Completion:

Water Level:

75 ft. below land surface on 2006-06-21

Measurement Method: Unknown

Packers: rubber 20'

rubber 130'

Submersible

Jetted

Pump Depth (ft.): 120

Well Tests:

Type of Pump:

Yield: 60 GPM with 85 ft. drawdown after 1 hours

1/31/2025 10:33:59 AM

Well Report Tracking Number 334696 Submitted on: 8/14/2013

Page 1 of 2

Water Quality:

Strata Depth (ft.)	Water Type	
132-160	fresh	

Chemical Analysis Made:

Did the driller knowingly penetrate any strata which contained injurious constituents?: No

Certification Data:

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information:

Driller Name: Henry Rangnow

License Number: 4276

Comments: ^MB

Report Amended on 7/9/2022 by Request #36931

Lithology: **DESCRIPTION & COLOR OF FORMATION MATERIAL**

Casing: **BLANK PIPE & WELL SCREEN DATA**

Top (ft.)	Bottom (ft.)	Description
0	2	surface soil
2	6	clay
6	12	caliche
12	30	sandstone
30	76	gravel
76	120	red clay
120	132	stone
132	160	water sand

Dia. (in.)	New/Used	Туре	Setting From/To (ft.)	
4" new	pvc plast	ic +1 1	/2 130'	
4" new pvc screen 130' 150' .014				
4" new	pvc cap 1	50'		

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540

CR Water Well Service

Customer	Name: Jeff	Smith	Date: 1-31-25
Add.			
Phone: w	ell inspectio	n	
Notes: Pla	ace off of HW	Y 87. water well in	4x6 pump house. A 3/4 HP set at 100' deep
pulling good	d amps good	plumbing over all. T	ank has the right amount of air in it. Pumping
good on the	e amount of w	ater it is doing.	
Qty	Size	F	Parts or Description