


NOTE: Aerial photograph is for visual exhibit purpose only. The accuracy of the photo shown in relationship to the established property lines is subject to an inherent unknown uncertainty.

"I affirm, under the penalties of perjury, that I have taken reasonable care to redact each social security number in this document, unless required by law."

Name: _____

LEGEND

- ▲ Section Corner Found (type as noted)
- 5/8" Rebar With Cap stamped PLS#20500020 Set
- Rebar Found
- ⊙ Mag nail Set
- ⊙ Mag/PK Nail found
- Railroad Spike found
- Railroad Spike Set
- ⊙ Iron Pipe Found
- Wood Corner Post Found
- (R) Record Deed Dimension
- R/W Right of Way
- X — Fenceline

LAND SURVEYORS CERTIFICATION:

This survey was performed wholly under the direction of Travis A. Norman, a Registered Land Surveyor, and to the best of my knowledge and belief was executed according to the survey requirements stated in 865 Indiana Administrative Code, 12-1 Minimum Standards for Competent Practice in Land Surveying.



TRAVIS A. NORMAN, PLS LS#20500020 DATE _____



TRAVIS NORMAN GROUP
LAND SURVEYING-AERIAL & LIDAR MAPPING

812-583-7864 OR 812-521-5553
1535 G STREET, BEDFORD, IN 47421

Date: 12/16/2024

Drawn by: TAN

Scale: 1" = 300'

Proj. #24-915

Checked by: TAN

Sheet 1 of 1