STATE OF TEXAS WELL REPORT for Tracking #625987

Owner: HSW LAND LLC Owner Well #: No Data

Address: **PO BOX 61341** Grid #: **56-46-6**

SAN ANGELO, TX 76906

Well Location: MOSEL RD Latitude: 30° 18' 18" N

HARPER, TX 78624 Longitude: 099° 15' 54" W

TRACT 4 Elevation: 2080 ft. above sea level

Well County: Gillespie

Type of Work: New Well Proposed Use: Domestic

Drilling Start Date: 10/20/2022 Drilling End Date: 10/20/2022

 Diameter (in.)
 Top Depth (ft.)
 Bottom Depth (ft.)

 Borehole:
 8
 0
 220

Drilling Method: Air Rotary

Borehole Completion: Open Hole

Annular Seal Data:

Top Depth (ft.)

Bottom Depth (ft.)

Description (number of sacks & material)

Cement 3.5 Bags/Sacks

5 50 Bentonite 12 Bags/Sacks

Seal Method: **Gravity** Distance to Property Line (ft.): **90'**

Sealed By: **Driller**Distance to Septic Field or other concentrated contamination (ft.): **N/A**

Distance to Septic Tank (ft.): N/A

Method of Verification: MEASURED

Surface Completion: Surface Sleeve Installed Surface Completion by Driller

Water Level: 74 ft. below land surface on 2022-10-20 Measurement Method: Sonic/Radar

Packers: Burlap at 50 ft.

Type of Pump: No Data

Well Tests: Pump Yield: 13 GPM with 0 ft. drawdown after 1 hours

Water Quality: Strata Depth (ft.) Water Type

To - 160 EDWARDS/GOOD

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the

driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in

the report(s) being returned for completion and resubmittal.

Company Information: PICKENS DRILLING CO.

P.O. BOX 543

HARPER, TX 78631

Driller Name: WILL PICKENS License Number: 54996

Comments: No Data

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing: BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description		
0	1	TOPSOIL		
1	10	CALICHE AND LIMESTONE		
10	80	SOLID LIMESTONE		
80	160	FRACTURED LIMESTONE, LOST RETURN		
160	220	SOLID LIMESTONE		

Dla (in.)	Туре	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
8.625	Riser	New Steel		2	2
4.5	Blank	New Plastic (PVC)	40	2	160
4.5	Perforated or Slotted	New Plastic (PVC)	40	160	220

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540