

STATE OF TEXAS WELL REPORT for Tracking #706679

Owner:	Cecil Andrews	Owner Well #:	1
Address:	P O Box 2089 Fredricksburg , TX 78624	Grid #:	57-26-9
Well Location:	5313 RR 965 Llano, TX 78643	Latitude:	30° 30' 31" N
Well County:	Llano	Longitude:	098° 46' 26" W
Number of Wells Drilled:	2	Elevation:	No Data

Type of Work:	New Well	Proposed Use:	Domestic
---------------	-----------------	---------------	-----------------

Drilling Start Date: **7/30/2025** Drilling End Date: **7/30/2025**

Borehole:	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
	8	0	38
	6.25	38	110

Drilling Method: **Air Hammer**

Borehole Completion: **Straight Wall**

Annular Seal Data:	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
	0	38	3 Benseal 4 Portland 7 Bags/Sacks

Seal Method: **Pressure**

Sealed By: **Driller**

Distance to Property Line (ft.): **50+**

Distance to Septic Field or other
concentrated contamination (ft.): **100+**

Distance to Septic Tank (ft.): **50+**

Method of Verification: **Land Owner**

Surface Completion:	Surface Sleeve Installed	Surface Completion by Driller
---------------------	---------------------------------	--------------------------------------

Water Level:	30 ft. below land surface on 2025-07-30	Measurement Method:	Sonic/Radar
--------------	--	---------------------	--------------------

Packers:	Burlap/Neoprene at 37 ft.
	Burlap/Neoprene at 38 ft.

Type of Pump: **No Data**

Well Tests:	Jetted	Yield: 6-7 GPM
-------------	---------------	-----------------------

Water Quality:

Strata Depth (ft.)	Water Type
38 - 102	Granite

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Apex Drilling, Inc.**
P.O. Box 867
Marble Falls, TX 78654

Driller Name: **Andrew Jackson Johnson**

License Number: **54989**

Apprentice Name: **Nathan Proctor**

Apprentice Number: **60615**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
0	1	Top Soil
1	50	Granite Gravel (H2o 38')
50	90	Tan Black Granite
90	110	Gray Tan Black Granite

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
4.5	Blank	New Plastic (PVC)	SDR17	2	30
4.5	Screen	New Plastic (PVC)	.035	30	50
4.5	Blank	New Plastic (PVC)	SDR17	50	70
4.5	Screen	New Plastic (PVC)	.035	70	110

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540