

STATE OF TEXAS WELL REPORT for Tracking #706680

Owner: **Cecil Andrews**

Owner Well #: **2**

Address: **P O Box 2089
Fredsrickberg, TX 78624**

Grid #: **57-26-9**

Well Location: **5313 RR 965
Llano, TX 78643**

Latitude: **30° 30' 24" N**

Longitude: **098° 46' 22" W**

Well County: **Llano**

Elevation: **No Data**

Number of Wells Drilled: **2**

Type of Work: **New Well**

Proposed Use: **Domestic**

Drilling Start Date: **7/30/2025**

Drilling End Date: **7/30/2025**

Borehole:

<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
8	0	70
6.25	70	180

Drilling Method: **Air Hammer**

Borehole Completion: **Straight Wall**

Annular Seal Data:

<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
0	65	3 Benseal 4 Portland 7 Bags/Sacks

Seal Method: **Pressure**

Distance to Property Line (ft.): **50+**

Sealed By: **Driller**

Distance to Septic Field or other
concentrated contamination (ft.): **100+**

Distance to Septic Tank (ft.): **50+**

Method of Verification: **Land Owner**

Surface Completion: **Surface Sleeve Installed**

Surface Completion by Driller

Water Level: **32 ft. below land surface on 2025-07-30**

Measurement Method: **Sonic/Radar**

Packers: **Burlap/Neoprene at 65 ft.
Burlap/Neoprene at 67 ft.**

Type of Pump: **No Data**

Well Tests: **Jetted Yield: 10 GPM**

Water Quality:

Strata Depth (ft.)	Water Type
65 - 67	Granite Gravel

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Apex Drilling, Inc.**
P.O. Box 867
Marble Falls, TX 78654

Driller Name: **Andrew Jackson Johnson**

License Number: **54989**

Apprentice Name: **Nathan Proctor**

Apprentice Number: **60615**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
0	1	Top Soil
1	18	Sandy Loam Clay
18	110	Gray Tan Granite (H2o 67')
110	130	Gray Green Tan Granite
130	165	Black Green Tan Gray Granite
165	180	Gray Granite Clay

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
4.5	Blank	New Plastic (PVC)	SDR17	2	120
4.5	Screen	New Plastic (PVC)	.035	120	180

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540