



WASTEWATER TREATMENT SYSTEM MAINTENANCE INSPECTION

Customer

The Zcar Group LLC

Permit Number

Site Address

22354 Farm to Market Road 306, Canyon Lake, TX 78133

Agency

Email

dave@arpusa.com

Phone

210-760-7292

County

Comal

System Details

Contract Period

Service Plan

Inspection Number

Date

March 20, 2024

INSPECTION

Equipment Inspection

Control Panel

Not Applicable

Disinfection Device

Not Applicable

Irrigation Pump

Not Applicable

Spray Field Vegetation

Operational

Aerator / Air Compressor

Not Applicable

Sprinkler / Drip Backwash

Not Applicable

Tests Results

Air Compressor PSI

Test Method

Grab

Air Compressor CFM

Color

Good

Chlorine Residual

Odor

Good

Sludge Levels

Tank 1

20

Tank 2

N/A

Tank 3

N/A

Tank 4

12/roots

Scum

Roots

Other Observations

Cleaned Air Filter?

☐

Inspection Port/Plug Secured?

☐

System Flushed?

☐

Repairs Made?

☒

Drip Filter Cleaned?

☐

Pump Filter Cleaned?

☐

Tank Lids Secured?

☒

Pumping Required?

☐

Additional Comments

Installed x2-20"-tank to lid adapters/ x2-20"x6" risers/ x2-20" lids/ x2
-50lbs bag quick dry concrete. Recommend pump out due to age of system and root intrusion. Need copper sulfate
added for roots in tank.

Andrew Bryan MT0002561

Inspector Name

March 20, 2024

Inspection Date

Luna Environmental / Ryan Seidensticker

Maintenance Provider Name

Ryan Seidensticker

License # MP0001708

Maintenance Provider Signature